

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

> GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:

Company Dennis Ware Controller

OGM Steve Demczak Environmental Scientist III

Inspection Report

Permit Number:	C0070038		
Inspection Type:	PARTIAL		
Inspection Date:	Wednesday, January 16, 2008		
Start Date/Time:	1/16/2008 2:00:00 PM		
End Date/Time:	1/16/2008 4:00:00 PM		
Last Inspection:	Wednesday, December 19, 2007		

Inspector: Steve Demczak, Environmental Scientist III Weather: Temp-15 deg, snow covered (12-18 inches)

InspectionID Report Number: 1542

Accepted by: dhaddock

Permitee: PLATEAU MINING CORP Operator: PLATEAU MINING CORP Site: WILLOW CREEK MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Mineral Ownership

Types of Operations

14,662.49 Total Permitted	✓ Federal	✓ Underground
71.44 Total Disturbed	☐ State	☐ Surface
Phase I	☐ County	✓ Loadout
Phase II	✓ Fee	☐ Processing
Phase III	✓ Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee notified the Division on May 7, 2007 that the second quarter of 2007 surface and UPDES water monitoring information for the Willow Creek Mine was in the electronic data base pipeline ready for uploading. only site having no flow was B-25 in Crandall Canyon.

The Permittee continues to meet the Special Condition included as Attachment "A" of the current State permit, which was renewed April 24, 2006.

There are no pending compliance actions.

There is currently no activity at this site.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Date

Wednesday, January 30, 2008

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070038 Inspection Type: PARTIAL

Inspection Date: Wednesday, January 16, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		\checkmark	
2.	Signs and Markers				
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	V		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓		V	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	V		✓	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	V		✓	
13.	Revegetation	V		V	
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	a Roads: Construction, Maintenance, Surfacing				
16.Ł	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		✓	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other		П		

Permit Number: C0070038
Inspection Type: PARTIAL

Inspection Date: Wednesday, January 16, 2008

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

No new permitting action has been submitted to the Division since the last inspection.

3. Topsoil

All topsoil has been used in reclamation.

4.a Hydrologic Balance: Diversions

Diversions were snow covered. No melting of snow was occurring.

4.d Hydrologic Balance: Water Monitoring

Water monitoring has been taken for the fourth quarter of 2007.

7. Coal Mine Waste, Refuse Piles, Impoundments

Refuse pile has been reclaimed.

8. Noncoal Waste

No non-coal waste material could be seen due to snow cover.

10. Slides and Other Damage

No slides were noticed during the inspection.

12. Backfilling And Grading

The site is backfilled and graded.

13. Revegetation

All vegetation is covered with snow.

18. Support Facilities, Utility Installations

There are no support facilities.